

## List of Environmental Reports and Documents Regarding Hazardous Materials

August 10, 2017

### Pier 70

1999 Annual Ground Water Monitoring Report for Piers 70 and 94, Tetra Tech, Inc., February 2000.

1999 Annual Ground Water Monitoring Report Piers 70 Tetra Tech Inc. 02-2000, Tetra Tech, Inc., February 2000.

Activity Summary Report, Pier 70, SCA Environmental, Inc., 8/5/02.

Annual Inspection Report for 2016, Pier 70 Risk Management Plan Area, Port of San Francisco, San Francisco, California, May 13, 2017.

Amended Report of Waste Discharge Pier 70 Solid Waste Disposal Site, The Mark Group 8-20-90, Mark Group, August 20, 1990.

Appendices F and G - Chemical and Physical Data Tables, Volume 2 of 3, Subchapter 15 Compliance, Pier 70, Solid Waste Disposal Site, Geo/Resource Consultants, Inc., December 1989.

Appendix H - Laboratory Data Reports, Volume 3 of 3, Subchapter 15 Compliance, Pier 70, Solid Waste Disposal Site, Geo/Resource Consultants, Inc., December 1989.

Article 22A Compliance; City Tow, Pier 70, San Francisco; PR0249798, Iris Environmental, January 9, 2004.

Article 22A Compliance; Former Car Crusher Building; Former City Tow, Pier 70; EHS-HWU Case Number 69, San Francisco Department of Public Health, September 1, 2005.

Asbestos Abatement Report, Pick Your Part, Inc. Pier 70, Iris Environmental, May 21, 2001, Iris Environmental, May 21, 2001.

Asbestos roof sampling report; Pier 70; building numbers 113 and 114, North Tower environmental, October 23, 2009.

Asbestos Survey SWL 349 Kiln, San Francisco Port Commission, 2/27/14.

Assessment of Suspect Asbestos-Containing Materials at the Pier 70 Office Building, 20th and Illinois Streets, Clayton Environmental Consultants, April 9, 1996.

BAE Systems San Francisco Ship Repair. Letter to Bay Area Air Quality Management District, Director of Compliance and Enforcement. Complaint of Paint Overspray., February 2015.

Certification Report; Pick Your Part, Inc.; Pier 70, San Francisco, CA, Iris Environmental, December 19, 2003.

Consent Decree executed November 11, 2011 between BAE Systems, Baykeeper, and Spaulding related to Baykeeper Complaint against BAE Systems in the United States District Court, Northern District Court of California (Case No. 3:11-cv-05184-SI) , Clean Water Act Violations.

Data Compilation Report & Appendices A through E Data Logs, Vol 1 of 3, Subchapter 15 Compliance, Pier 70 Solid Waste Disposal Site, Geo/Resource Consultants, Inc., December 1989.

Draft Over the Water Operations Manual, Puglia Marine San Francisco Shipyard, February 2017.

Environmental Health & Safety Plan, Pier 70, San Francisco, California, Acumen Industrial Hygiene, December 2015.

Environmental Risk Management Plan, Pier 70 Master Plan Area, Pier 70 Master Plan Area, Treadwell & Rollo, 7/25/13.

Environmental Site Investigation Report, Pier 70 Master Plan Area, Treadwell & Rollo, 1/13/11.

Feasibility Study and Remedial Action Plan, Crane Cove Park Nearshore Sediment, Langan, 3/31/15.

Final Summary Report, Soil Boring Sampling and Well Installation for Pier 70 Building PCB Remedial Investigation, Pier 70 Mixed Use Opportunity Area Engineering/Remediation Resources Group, Inc. Nov. 2005, Engineering/Remediation Resources Group, Inc., November 2005.

GeoResource Data Compilation & Appendices A through E Data Logs Report Vol. 1 of 3 Subchapter 15 Pier 70 Solid Waste Disposal Site, December 1989, Geo/Resource Consultants, Inc., December 1989.

Groundwater Data Summary and Request to Rescind Waste Discharge Requirements; Pier 70 (Order 87-060) and Pier 94 (Order 87-061 Disposal Sites / Port of San Francisco, Port of San Francisco, August 17, 1999.

Hazardous material abatement; General clean up, ACM abatement and lead-based paint stabilization; Building 101, Pier 70, EnviroSurvey, Inc., July 16, 2010.

Hazardous Materials Business Plan, Puglia Engineering Inc., San Francisco Shipyard, February 2017.

Hazardous Materials Inspection Report, Pier 70, Building 12, Van Brunt Associates, 05/22/14.

Hazardous Materials Investigation of the Mariposa Facilities Project Area, July 1990, ERM-West, Inc., July, 1990.

Hazardous Materials Survey Report; Pier 70 Renovation Project, Building 101, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project, Building 115/116, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project, Building 50, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project; Building 110, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project; Building 14, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project; Building 2, Winzler & Kelly, December 16, 2011.

HAZARDOUS MATERIALS SURVEY REPORT; Pier 70 Renovation Project; Crane 30, Crane 14, & Street Tower, GHD Inc., January 28, 2012.

Hazardous Materials Survey Report; Pier 70 renovation; Building 102 powerhouse, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation; Building 104, Winzler & Kelly, 12-16-2012.

Hazardous materials survey; Pier 70 Renovation; Building 114, Winzler & Kelly, December 16, 2011.

Health and Safety Plan & Dust Control Mitigation and Monitoring Plan for Utility Installation and Soil Load Out Activities, Building 116 at Pier 70, SCA Environmental, Inc., 10/13/2009.

Industrial Activities Storm Water Pollution Prevention Plan, Puglia Engineering, Inc., San Francisco Shipyard, February 2017.

Interim Progress Report & Request for Extension, Pier 70 Risk Management Plan Area, Port of San Francisco, San Francisco, California, November 4, 2016.

Investigation of PG&E ZA-1 Line Alignment, Unit 3 Power Generation Area, Potrero Power Plant Site, Haley & Aldrich, 10/20/14.

Level 1 Exceedance Response Action (ERA) Report, BAE Systems San Francisco Ship Repair, Inc., December 29, 2016.

Major Facility Review Permit, Puglia Engineering, Inc. San Francisco Shipyard, Facility #A3288, Bay Area Air Quality Management District, San Francisco, California, February 2017.

Oil Spill Contingency Plan, Puglia Engineering San Francisco Shipyard, April 2017.

Order No. 00-030 / Rescission of Waste Discharge Requirements in Order No. 87-060; City and County of San Francisco / Pier 70 Class III Landfill, California Regional Water Quality Control Board, April 20, 2000.

Order No. 87-060 Updated Requirements; City and County of San Francisco / Pier 70 Class III Landfill, California Regional Water Quality Control Board, 1987.

PCB Removal, Corrective Action Plan, Pier 70, Building 50, Engineering-Remediation Resources Group, Inc. August 2003, Engineering/Remediation Resources Group, Inc., August 2003.

Phase 1 Environmental Site Assessment for Pier 70, Mixed Use Opportunity Area, Corner of Illinois Street and 20th Street, Vol. I of II, Environmental Site Assessment, Tetra Tech, Inc., August 1998.

Phase 1 Environmental Site Assessment for Pier 70, Mixed Use Opportunity Area, Corner of Illinois Street and 20th Street, Vol. II of II, Supplemental Documents, Tetra Tech, Inc., August 1998.

Phase I Brownfields, Environmental Site Assessment Report Pier 70, Ecology and Environment, Inc., March 2000.

Phase I Environmental Site Assessment for Pier 70 Maritime Use Area. Ecology and Environmental, Inc. March 2001, Ecology and Environment, Inc., March 2001.

Phase I Environmental Site Assessment for Pier 70, Mixed Use Opportunity Area, Corner Of Illinois Street and 20th Street. Tetra Tech, Inc. August 1998 (Vol. I), Tetra Tech, Inc., August 1998.

Phase I Environmental Site Assessment for Pier 70, Mixed Use Opportunity Area, Corner Of Illinois Street and 20th Street. Tetra Tech, Inc. August 1998 (Vol. II), Tetra Tech, Inc., August 1998.

Draft Phase I Environmental Site Assessment for Pier 70 Waterfront Site, San Francisco, California, Geosyntec Consultants, November 2011.

Phase I Environmental Site Assessment, One-Acre Parcel on SWL 349, Pier 70. Iris Environmental, October 23, 2003, Iris Environmental, October 23, 2003.

Phase II Corrective Action Plan, PCB Removal Action, Port of San Francisco, Pier 70, Building 50. Engineering-Remediation Resources Group, Inc. June 2006, Engineering/Remediation Resources Group, Inc., June 2006.

Pier 70 Mixed Use Opportunity Area, PCB Assessment, Targeted Brownfields Assessment Report, Ecology and Environment, Inc., 1/9/03.

Pier 70 Mixed Use Opportunity Area, Phase II, Targeted Brownfields Assessment Report. Ecology and Environment, Inc. November 2000, Ecology and Environment, Inc., November 2000.

Pier 70 mixed Used Opportunity Area PCB Assessment, Targeted Brownfields Assessment Report, Ecology and Environmental, Inc. January 2003, Ecology and Environment, Inc., January 2003.

Pier 70 Mixed Use Opportunity area, Expanded Phase II Target Brownfields Assessment Report. Ecology and Environment, Inc. January 2004, Ecology and Environment, Inc., January 2004.

Pier 70, Building 101 Cleanup, ACC Environmental Consultants, February 22, 1996.

Pier 70, Mixed Use Opportunity Area, Phase II Brownfields Targeted Site Assessment, Draft Sampling and Analysis Plan, Ecology and Environment, Inc., August 2002.

Pier 70, Mixed Use Opportunity Area, Phase II Brownfields, Targeted Site Assessment Report, Ecology and Environment, Inc., November 2000.

Pier 70, Mixed Use Opportunity Area, Phase II Brownfields, Targeted Site Assessment, Sampling and Analysis Plan, Ecology and Environment, Inc., June 2000.

Progress Report 2013, Pier 70 Risk Management Plan, Port of San Francisco, San Francisco, California, July 31, 2014.

Removal of Underground Tanks, Pier 70, Harding Lawson Associates, March 31, 1988.

Sample Analysis Plan, Pier 70 Building 50 PCB Remedial Investigation, Pier 70 Mixed Use Opportunity Area, Engineering Remediation Resources Group Inc, September 2004, Engineering/Remediation Resources Group, Inc., September 2004.

Sampling and Analytical Report, Pier 70, Building 6, Curtis & Tompkins, LTD, November 1983.

Semi-Annual National Emission Standards for Hazardous Air Pollutants (NESHAP) Compliance Report for January 1 – June 30, 2016, BAE Systems San Francisco Ship Repair, July 2016.

Site Evaluation Report and Site Mitigation Plan, Pier 70 Waterfront Site, Geosyntec, 8/31/15.

Site History Report and Work Plan City Tow, Pier 70, Iris Environmental, Inc. February 7, 2002, Iris Environmental, February 7, 2002.

Site History Report and Work Plan, City Tow, Pier 70, Iris Environmental, February 7, 2002.

Site Investigation Report, Former Crusher Building, Pick Your Part, Inc. Pier 70, Iris Environmental, July 13, 2004, Iris Environmental, July 13, 2004.

Soil Remediation Report, Pick Your Part, Inc. Pier 70, Iris Environmental, December 12, 2001, Iris Environmental, December 12, 2001.

Soil Remediation Report, Pick Your Part, Inc., Pier 70, Iris Environmental, December 12, 2000.

Soils Analysis Report and Mitigation Plan For The City Tow Facility; Pier 70, San Francisco, CA, San Francisco Department of Public Health, July 29, 2002.

Soils Analysis Report and Mitigation Plan, City Tow, Pier 70, Iris Environmental, 7/10/02.

Soils Analysis Report and Mitigation Plan; City Tow; Pier 70, San Francisco PR0249798, San Francisco Department of Public Health, October 10, 2002.

Soils Analysis Report and Site Mitigation Plan, Pick Your Part, Inc. [City Tow], Pier 70, Iris Environmental, July 10, 2002, Iris Environmental, July 10, 2002.

Spill Prevention Control and Countermeasure Plan, BAE San Francisco Ship Repair, December 1, 2016.

Stormwater Annual Comprehensive Facility Compliance Evaluation, BAE San Francisco Ship Repair, June 30, 2016.

Submittals For: Pier 70, Corner of 20th and Illinois, Bluewater Environmental Services, 1992-1996.

Subsurface Investigation at Illinois and 20th Streets (site), Tetra Tech, Inc., 4/13/99.

Subsurface Investigation for Port of San Francisco, Pier 70. Tetra Tech, Inc., December 1997, Tetra Tech, Inc., December 1997.

Subsurface Investigation, Pier 70, Tetra Tech, Inc., December 1997.

Summary Report: Asbestos and Lead-Based Paint Survey, Pier 70, Buildings 36, 40, 101, 102, 104 and 109, 20th and Illinois Streets, SCA Environmental, Inc., May 1998.

Summary Report: Bulk Asbestos and Exterior Paint Survey, Pier 70, Building 104, SCA Environmental, Inc., October 1999.

Summary Report: Bulk Asbestos and Lead-Based Paint Survey, Building 111, Pier 70, SCA Environmental, Inc., March 1995.

Summary Report: Bulk Asbestos and Lead-Based Paint Survey, Pier 70 Crane #30, SCA Environmental, Inc., February 1996.

Summary report: hazardous Materials Assessment, Port of SF Pier 70 Building 21, SCA Environmental, Inc., 4/2008.

Supplement Investigation Report Former Car Crusher Building Former City Tow- Pier 70, Iris Environmental, March 3, 2005, Iris Environmental, March 3, 2005.

Survey for Asbestos and Lead-Based Paint; Noonan Building (Building #11); Pier 70; SCA Project No: B-7265, SCA Environmental, Inc., 9/2/2005.

Survey Report and Demolition and Renovation Cost Estimates; Pier 70 Building 50, SCA Environmental, Inc., January 14, 2013.

Wipe Sample Procedures & Analysis; Pier 70 Re-development Project, Nova Abatement & Construction Services, Inc., May 2, 2012.

**Seawall Lot 349**

Analysis of Bay Discharge, North Embarcadero Roadway Project, Camp Dresser & McKee, 9/27/94.

Article 22A Compliance; City Tow, Pier 70, San Francisco; PR0249798, Iris Environmental, January 9, 2004.

Article 22A Compliance; Former Car Crusher Building; Former City Tow, Pier 70; EHS-HWU Case Number 69, San Francisco Department of Public Health, September 1, 2005.

Asbestos roof sampling report; Pier 70; building numbers 113 and 114, North Tower environmental, October 23, 2009.

Asbestos Survey SWL 349 Kiln, San Francisco Port Commission, 2/27/14.

BAE Systems San Francisco Ship Repair. Letter to Bay Area Air Quality Management District, Director of Compliance and Enforcement. Complaint of Paint Overspray., February 2015.

Bunker Oil Characterization, North Embarcadero Roadway and F-Line Extension, Camp Dresser & McKee, 12/29/95.

Certification Report; Pick Your Part, Inc.; Pier 70, San Francisco, CA, Iris Environmental, December 19, 2003.

Embarcadero Roadway Urban Design Project, Hazardous Waste Investigation, Site History Report, Bechtel Environmental, Inc., August 11, 1989.

Embarcadero Roadway Urban Design Project, Rincon Point Block, Sampling And Testing Plan, Geo/Resource Consultants, Inc., October 16, 1989.

Environmental Risk Management Plan, Pier 70 Master Plan Area, Pier 70 Master Plan Area, Treadwell & Rollo, 7/25/13.

Geotechnical Investigation, Mariposa Storage/Transport Facilities, AGS, Inc., June 1989.

Groundwater Data Summary and Request to Rescind Waste Discharge Requirements; Pier 70 (Order 87-060) and Pier 94 (Order 87-061 Disposal Sites / Port of San Francisco, Port of San Francisco, August 17, 1999.

Hazardous Materials Monitoring and Management Plans, Mariposa Facilities Project, ERM-West, Inc., 1/31/92.

### **Seawall Lot 3491**

Environmental Risk Management Plan, Pier 70 Master Plan Area, Pier 70 Master Plan Area, Treadwell & Rollo, 7/25/13.

Hazardous material abatement; General clean up, ACM abatement and lead-based paint stabilization; Building 101, Pier 70, EnviroSurvey, Inc., July 16, 2010.

### **Pier 68**

Environmental Risk Management Plan, Pier 70 Master Plan Area, Pier 70 Master Plan Area, Treadwell & Rollo, 7/25/13.

Environmental Site Investigation Report, Pier 70 Master Plan Area, Treadwell & Rollo, 1/13/11.

Envirosurvey, 7/16/10, Hazardous Material Abatement, General Cleanup., envirosurvey Inc., July 16, 2010.

Feasibility Study and Remedial Action Plan, Crane Cove Park Nearshore Sediment, Langan, 3/31/15.

Hazardous material abatement; General clean up, ACM abatement and lead-based paint stabilization; Building 101, Pier 70, EnviroSurvey, Inc., July 16, 2010.

Hazardous Materials Survey Report; Pier 70 Renovation Project, Building 101, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation Project; Building 110, Winzler & Kelly, December 16, 2011.

HAZARDOUS MATERIALS SURVEY REPORT; Pier 70 Renovation Project; Crane 30, Crane 14, & Street Tower, GHD Inc., January 28, 2012.

Hazardous Materials Survey Report; Pier 70 renovation; Building 102 powerhouse, Winzler & Kelly, December 16, 2011.

Hazardous Materials Survey Report; Pier 70 Renovation; Building 104, Winzler & Kelly, 12-16-2012.

Miscellaneous Documents Pertaining to PCB Remediation, Port of San Francisco, 2007.

PCB Remediation Work Plan and Phase II Corrective Action Plan / PCB Removal Action

Port of San Francisco / Pier 70, Building 50, San Francisco Department of Public Works, July 2007.

Pier 68 Abandoned Hazardous Waste, Port of San Francisco, 3/1/07.



Wipe Sample Procedures & Analysis; Pier 70 Re-development Project, Nova Abatement & Construction Services, Inc., May 2, 2012.