



| NO. | REVISIONS | DATE | APPROVED |
|-----|-----------|------|----------|
| 1 | | | |



(Looking from Inside)


Drydock Frames



(Looking from Inside)

Drydock Frames

Repaired 2013



| PRINCIPAL CHARACTERISTICS | |
|---------------------------|--------|
| LENGTH OVERALL | 90'-0" |
| BREADTH | 18'-0" |
| DEPTH | 6'-0" |

| NO. | DATE | DESCRIPTION | BY | CHKD. |
|-----|----------|-----------------------|----|-------|
| 1 | 02/03/17 | EAST WINGWALL REPAIRS | | |

EAST WINGWALL REPAIRS

SHEET 1 OF 1